

HUO 510

Standalone job list

Front destination box (ordered list)

1. Repair frame
2. Clean and paint inside
3. Rewire and fit new bulbs
4. Fit blind
5. Fit new glass and beading

Boot

- Refurbish boot light and refit
- Fit lino
- Install wiring components (switch, boot light, junction boxes)
- Finish doors with bendy ply inner skin, fittings and paint
- Hang doors
- ~~install new drip rail~~
- install gland and conduit from front to rear (see chassis)

Cab

1. Remove drivers seat and refurbish
2. Replace incorrect wing
3. Repair any steelwork needed
 - Install wiring conduit and gland in rear wall for rear lighting
 - Install conduit and glands for front lights
 - Obtain and fit saloon window glass
 - General clean and repaint

Entrance door

1. Strip and repaint exterior
2. Photograph used tickets lettering and create replacements
3. Clean and paint interior side, ticket box

Chassis

1. Remove fuel tank
2. Clean and silver off side frame inside and outside
3. Install wiring conduit (see cab)
4. Repaint fuel tank, determine if filler is correct and alter it if not

Engine

1. Remove radiator
2. Replace gasket for bottom hose connection
3. Replace existing incorrect fan with correct fan
4. Refit and adjust position of radiator
5. Service engine (oil change etc.)

Roof

- Vactan the ventilators
- Fill and sand the repair over the entrance

Interior

- Refit beading to rear corner panels
- Refit rear seat back